

**Highway Tree safety related felling list, Novemebr 2024**

St Albans City & District Council carry out a three-year cycle of safety surveys, and the safety related work on Highway trees on behalf of Hertfordshire County Council.

Sometimes it is necessary to remove trees that are dead, dying or have significant structural weaknesses. When the trees are felled, usually the stumps are left in-situ at about a metre high so they are clearly visible. The stumps are then ground out in the subsequent months and the area is re soiled and seeded as necessary.

Before any work starts the contractor will check each tree for nesting birds. If active nests are present the work will be postponed if it is safe to do so.

Tree Number	Work Order	Location	County Division	District Ward	Road Name	Closest Property	Species	Reason	Work type	Checked on Site	Work Target Month
14	HT2425-024	St Albans	St Albans South	Verulam	Abbey Avenue, Verulam, St Albans	Outside 21	Downy birch	Poor structural and physical condition	Planned	In progress	Dec / Feb
404	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Opposite Emfield Lodge	Common holly	Poor structural and physical condition	Planned	In progress	Dec / Feb
425	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
426	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
431	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
432	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
433	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
435	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
436	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
437	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
449	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
450	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ambrose Lane, Harpenden	Roadside hedge line between Bloomfield Rad and Elmfield Lodge	English elm	Dead Tree	Planned	In progress	Dec / Feb
1079	HT2425-020	St Albans	St Albans North	Batchwood	Batchwood, St Albans	From lamp 328 to 327	Acer pseudoplatanus	Dead Tree	Planned	In progress	Dec / Feb
1161	HT2425-008	St Albans	St Albans North	Batchwood	Batchwood, St Albans	From lamp 325 to 323	Fagus sylvatica (Common Beech)	Dead Tree	Planned	In progress	December
1380	HT2425-020	St Albans	St Albans North	Batchwood	Batchwood, St Albans	From lamp 327 to 326	Sambucus nigra (Elder)	Dead Tree	Planned	In progress	Dec / Feb
1384	HT2425-008	St Albans	St Albans North	Batchwood	Batchwood, St Albans	Outside 59	Sorbus aucuparia (Rowan/Mountain Ash)	Dead Tree	Planned	In progress	December
1919	HT2425-020	St Albans	St Albans East	Cunningham	Blake Close, St Albans	To the side of 11 Admirals Walk	Malus sp. (Apple sp.)	due to evident decline. Limited live growth left.	Planned	In progress	Dec / Feb
2230	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Bullens Green Lane, Colney Heath	Outside 10-12	Sorbus cashmiriana (Kashmir Rowan)	Dead Tree	Planned	In progress	Dec / Feb
2750	HT2425-020	St Albans	St Albans East	Cunningham	Cell Barnes Lane, St Albans	Opposite 5	Malus sylvestris (Wild Crab)	Due to poor structural/physiological condition in order to prevent failure on to road footpath.	Planned	In progress	Dec / Feb
2798	HT2425-008	St Albans	St Albans East	Cunningham	Cell Barnes Lane, St Albans	Opposite 22 Aldwick Court	Tilia x vulgaris (Common Lime)	Dead Tree	Planned	In progress	December

3421	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Church Lane, Colney Heath	Opposite St Marks Church	Prunus sp. (Cherry sp.)	Dead Tree	Planned	In progress	Dec / Feb
3423	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Church Lane, Colney Heath	Boundary of St Marks Church	Quercus robur (English Oak)	Dead Tree	Planned	In progress	Dec / Feb
3439	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Church Lane, Colney Heath	Opposite St Marks Church	Sorbus sp. (Sorbus sp.)	Dead Tree	Planned	In progress	Dec / Feb
4041	HT2425-024	St Albans	St Albans South	Verulam	Corder Close, St Albans	Outside 16	Rowan	Dead Tree	Planned	In progress	Dec / Feb
4041	HT2425-020	St Albans	St Albans South	Verulam	Corder Close, St Albans	Outside 16	Sorbus aucuparia (Rowan/Mountain Ash)	Dead Tree	Planned	In progress	Dec / Feb
5432	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Outside 1-2	Common ash	Poor structural and physiological condition	Planned	In progress	Dec / Feb
5467	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Opposite 5	Elder	Poor structural and physiological condition	Planned	In progress	Dec / Feb
5488	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Opposite rear of 39 White Hedge Drive	English elm	Dead Tree	Planned	In progress	Dec / Feb
5491	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Adjacent to 25 Temple View	English elm	Dead Tree	Planned	In progress	Dec / Feb
5492	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Rear of 9 Temple View	English elm	Dead Tree	Planned	In progress	Dec / Feb
5508	HT2425-022	Harpenden	Harpenden South West	Harpenden West	Fairmead Avenue, Harpenden	Outside 1	Norway maple	Dead Tree	Planned	In progress	Dec / Feb
5622	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Fellowes Lane, Colney Heath	On triangular green Opposite 22	Prunus cerasifera 'Atropurpurea' (Cherry Plum (Myrobalan))	Due to fungal colonisation at base and poor structural/physiological condition in order to prevent failure on to road and car parking.n	Planned	In progress	Dec / Feb
6619	HT2425-020	St Albans	St Albans East	Cunningham	Grasmere Road, St Albans	Opposite 8	Prunus cerasifera 'Nigra' (Purple Cherry Plum)	Due to poor structural/physiological condition.	Planned	In progress	Dec / Feb
8614	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Near junction of London Road and Colindale Ave	Poplar	Dead Tree	Planned	In progress	Dec / Feb
9585	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans		Pedunculata oak	Dead Tree	Planned	In progress	Dec / Feb
9616	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Opposite entrance to London road Cemetery	Common hawthorn	Dead Tree	Planned	In progress	Dec / Feb
10043	HT2425-019	St Albans	London Colney	Colney Heath	Highfield Lane, Tyttenhanger, St Albans	From double bend to A414	Fraxinus excelsior (Ash)	Heavily declining Ash to prevent failure onto road.	Planned	In progress	Dec / Feb
10982	HT2425-019	Bricket Wood	St Stephen's	St Stephen	Hyburn Close, Bricket Wood	adjacent to 7	Acer platanoides (Norway Maple)	Poor structural condition	Planned	In progress	Dec / Feb
11029	HT2425-024	St Albans	St Albans South	Verulam	Jerome Drive, St Albans	Opposite 34	Norway maple	Due to decline since last survey, poor structure condition and to prevent failure in to the highway	Planned	In progress	Dec / Feb
11034	HT2425-020	St Albans	St Albans South	Verulam	Jerome Drive, St Albans	Outside 8.10	Betula sp. (Birch)	Due to decay in principle stem and likelihood for failure of one remaining limb onto parked cars.	Planned	In progress	Dec / Feb
11034	HT2425-024	St Albans	St Albans South	Verulam	Jerome Drive, St Albans	Outside 8.10	Birch	In decline and poor structural and phycological condition	Planned	In progress	Dec / Feb
11077	HT2425-020	St Albans	St Albans South	Verulam	King Harry Lane, St Albans	Side of 10 Parklands Drive	Corylus avellana (Common Hazel)	Dead Tree	Planned	In progress	Dec / Feb
11289	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Opposite 12-14	Common ash	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11292	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 13	Apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11293	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 13	Apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11294	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 33	Apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb

11295	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 37	Apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11302	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 60	Crab apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11303	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 60	Crab apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11304	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 40	Crab apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11305	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 38	Crab apple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
11598	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Footpath within falling distance of tree adjacent to 334 Watford Road	Pedunculate oak	Dead Tree	Planned	In progress	Dec / Feb
12854	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Long Fallow, Bricket Wood		Prunus	Dead Tree	Planned	In progress	Dec / Feb
14781	HT2425-008	Harpenden	Harpenden North East	Harpenden East	Lyndhurst Close, Harpenden	Outside 10	Aesculus hippocastanum (Horse Chestnut)	Due to poor structural and physiological condition	Planned	In progress	December
15283	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Outside Green Hedges Marshalls Heath Lane	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
15285	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Outside Green Hedges Marshalls Heath Lane	Common ash	Poor structural condition	Planned	In progress	Dec / Feb
15493	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	In decline and poor structural and physiological condition	Planned	In progress	Dec / Feb
15495	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
15519	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite 7 Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
15671	HT2425-020	St Albans	St Albans South	Verulam	Mayne Avenue, St Albans	Rear of 2 Samian Gate	Alnus glutinosa (Common Alder)	Dead Tree	Planned	In progress	Dec / Feb
15729	HT2425-024	St Albans	St Albans South	Verulam	Mayne Avenue, St Albans	Outside carpark adjacent to Waitrose car park	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
15768	HT2425-024	St Albans	St Albans South	Verulam	Mayne Avenue, St Albans	Opposite 1 Flavian Close	Rowan	Dead Tree	Planned	In progress	Dec / Feb
15795	HT2425-020	St Albans	Colney Heath & Marshalswick	Marshalswick East & Jersey Farm	Meadow Close, St Albans	Meadow Close, Marshalswick North	Prunus sp. (Cherry sp.)	Dead Tree	Planned	In progress	Dec / Feb
15903	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Medlows, Harpenden	Rear of 23 Roundwood Park	Aspen	Dead Tree	Planned	In progress	Dec / Feb
15905	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Medlows, Harpenden	Rear of 25 Roundwood Park	Aspen	Dead Tree	Planned	In progress	Dec / Feb
16658	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite 30	Acer campestre (Field Maple)	Due to poor physiological condition with decay	Planned	In progress	December
16681	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite 24	Crataegus monogyna (Common Hawthorn/Quick/May)	Dead Tree	Planned	In progress	December
16687	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite 26	Fraxinus excelsior (Ash)	Due to poor structural and physiological condition and ash dieback	Planned	In progress	December
16688	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite 26	Fraxinus excelsior (Ash)	Due to Ash die back	Planned	In progress	December
16694	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite the Childrens Nursery	Ilex aquifolium (Holly)	Dead Tree	Planned	In progress	December
16705	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite 36	Prunus sp. (Cherry sp.)	Due to poor structural and physiological condition	Planned	In progress	December
16706	HT2425-008	Harpenden	Harpenden South West	Harpenden West	Moreton End Lane, Harpenden	Opposite 36	Prunus sp. (Cherry sp.)	Due to poor structural and physiological condition	Planned	In progress	December

16787	HT2425-020	St Albans	St Albans East	Cunningham	Nelson Avenue, St Albans	Opposite 33	Cerasus avium (Wild Cherry)	Due to fungal colonisation at base and poor structural/physiological condition in order to prevent failure on to road	Planned	In progress	Dec / Feb
16808	HT2425-008	St Albans	St Albans South	Verulam	Netherway, St Albans	Left of 1 Allandale	Populus nigra 'Italica' (Lomardy Poplar)	Due to poor structural condition and to prevent failure in to the road	Planned	In progress	December
17001	HT2425-025	St Albans	St Albans East	Cunningham	Nightingale Lane, London Colney	To the side of 1 Nightingale Lane	Common laburnum	Dead Tree	Planned	In progress	Dec / Feb
17079	HT2425-024	Bricket Wood	St Stephen's	St Stephen	North Riding, Bricket Wood	outside 7	Prunus	Dead Tree	Planned	In progress	Dec / Feb
17356	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Oaklands Lane, Smallford	Opposite 30 Oaklands Lane	Acer campestre (Field Maple)	Dead Tree	Planned	In progress	Dec / Feb
17657	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ox Lane, Harpenden	Outside 1	English elm	Dead Tree	Planned	In progress	Dec / Feb
17675	HT2425-023	St Albans	St Albans North	Batchwood	Oysterfields, St Albans	Adjacent to 182 Redbourn Road	English elm	Dead Tree	Planned	In progress	Dec / Feb
18304	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Reedham Close, Bricket Wood	adjacent to 6 Meadow Close	Common hawthorn	Dead Tree	Planned	In progress	Dec / Feb
18314	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Reedham Close, Bricket Wood	adjacent to 2 Meadow Close	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
18915	HT2425-025	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Harper Lane, Shenley, Radlett	Adjacent to Fairfolds	English elm	Dead Tree	Planned	In progress	Dec / Feb
18916	HT2425-025	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Roestock Lane, Colney Heath	Adjacent to Fairfolds	English elm	Dead Tree	Planned	In progress	Dec / Feb
18918	HT2425-025	Radlett	Colney Heath & Marshalswick	Colney Heath	Harper Lane, Shenley, Radlett	Adjacent to Fairfolds	English elm	Dead Tree	Planned	In progress	Dec / Feb
18920	HT2425-025	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Harper Lane, Shenley, Radlett	Adjacent to Fairfolds	English elm	Dead Tree	Planned	In progress	Dec / Feb
19184	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Roundwood Park, Harpenden	Outside 48A	Common lime	Due to poor structural condition	Planned	In progress	Dec / Feb
19192	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Roundwood Park, Harpenden	Outside 45	Common lime	Due to poor structural condition	Planned	In progress	Dec / Feb
19331	HT2425-022	Harpenden	Harpenden South West	Harpenden West	Salisbury Avenue, Harpenden	Outside 7	Caucasian lime	Due to poor structural condition	Planned	In progress	Dec / Feb
19348	HT2425-022	Harpenden	Harpenden South West	Harpenden West	Salisbury Avenue, Harpenden	Outside 13	Caucasian lime	Due to poor structural condition	Planned	In progress	Dec / Feb
19350	HT2425-022	Wheathampstead	Harpenden South West	Harpenden West	Salisbury Avenue, Harpenden	Outside 10a	Caucasian lime	Fair	Planned	In progress	Dec / Feb
19360	HT2425-022	Harpenden	Harpenden South West	Harpenden West	Salisbury Avenue, Harpenden	Opposite The Bourne	Caucasian lime	Due to poor structural condition	Planned	In progress	Dec / Feb
21763	HT2425-020	St Albans	Colney Heath & Marshalswick	Marshalswick East & Jersey Farm	Sherwood Avenue, St Albans	Opposite 158 The Ridgeway	Cerasus avium (Wild Cherry)	Due to poor structural/physiological condition.	Planned	In progress	Dec / Feb
21853	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Sleepshyde, Smallford	Outside 5	Prunus cerasifera 'Pissardii' (Pissard's Plum)	Due to extent of decay fungi presence in tree, which will likely cause further branch failure over time.	Planned	In progress	Dec / Feb
21853	HT2425-008	Smallford	Colney Heath & Marshalswick	Colney Heath	Sleepshyde, Smallford	Outside 5	Prunus cerasifera 'Pissardii' (Pissard's Plum)	Due to extent of decay fungi presence in tree, which will likely cause further branch failure over time. Leave 1 m stump.	Planned	In progress	December
21944	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Smallford Lane, Smallford	Outside 1.2	Crataegus monogyna (Common Hawthorn/Quick/May)	Dead Tree	Planned	In progress	Dec / Feb
22406	HT2425-020	St Albans	St Albans East	Cunningham	St Vincent Drive, St Albans	Opposite 47	Cerasus serrulata (Japanese Cherry)	Due to poor structural/physiological condition.	Planned	In progress	Dec / Feb

22448	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Stanley Avenue, Bricket Wood	Outside 15	Apple	Dead Tree	Planned	In progress	Dec / Feb
22642	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Sunnydell, Bricket Wood	outside 8	Prunus	Dead Tree	Planned	In progress	Dec / Feb
22879	HT2425-022	Harpenden	Harpenden South West	Harpenden South	The Chowns, Harpenden	Outside 3	Flowering cherry	Due to poor structural condition and declining crown	Planned	In progress	Dec / Feb
23131	HT2425-020	St Albans	Colney Heath & Marshalswick	Marshalswick East & Jersey Farm	The Ridgeway, St Albans	Opposite 210	Cerasus serrulata (Japanese Cherry)	Due to poor structural/physiological condition.	Planned	In progress	Dec / Feb
23231	HT2425-022	Harpenden	Harpenden South West	Harpenden South	The Uplands, Harpenden	Opposite 33 West Common Way	Lawson cypress	Fair	Planned	In progress	Dec / Feb
23291	HT2425-020	St Albans	St Albans East	Cunningham	Thirlmere Drive, St Albans	Opposite 67	Betula pubescens (Downy Birch)	Dead Tree	Planned	In progress	Dec / Feb
23411	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Tippendell Lane, Bricket Wood	opposite 60 Tippendell Lane	Prunus	Dead Tree	Planned	In progress	Dec / Feb
23554	HT2425-020	St Albans	St Albans South	Sopwell	Trumpington Drive, St Albans	Outside 26	Prunus cerasifera (Cherry Plum (Myrobalan))	Due to poor structural/physiological condition.	Planned	In progress	Dec / Feb
24575	HT2425-022	Harpenden	Harpenden North East	Harpenden East	West Way, Harpenden	Outside 21	Prunus	Dead Tree	Planned	In progress	Dec / Feb
24683	HT2425-024	St Albans	St Albans South	Verulam	Westfields, St Albans	Outside 17	Rowan	Dead Tree	Planned	In progress	Dec / Feb
24731	HT2425-008	Harpenden	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 98	Acer campestre (Field Maple)	Dead Tree	Planned	In progress	December
24779	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 94	Ilex aquifolium (Holly)	Dead Tree	Planned	In progress	December
24783	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 96	unrecognized (Unrecognised)	Dead Tree	Planned	In progress	December
24933	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 96	unrecognized (Unrecognised)	Dead Tree	Planned	In progress	December
24947	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Wheatlock Mead, Redbourn	Opposite 2 Wheatlock Mead	Rowan	Dead Tree	Planned	In progress	Dec / Feb
25458	HT2425-020	St Albans	St Albans East	Cunningham	Whitecroft, St Albans	London Road at junction with Herons Way	Acer pseudoplatanus (Sycamore)	Due to poor structural/physiological condition in order to prevent failure on to road/ footpath/ third party land.	Planned	In progress	Dec / Feb
25873	HT2425-020	St Albans	St Albans South	Verulam	Windridge Close, St Albans	Opposite 10	Robinia pseudoacacia (False Acacia sp./Black Locust)	Due to poor structural/physiological condition.	Planned	In progress	Dec / Feb
26002	HT2425-020	St Albans	St Albans East	Hill End	Woodland Drive, St Albans	Opposite 7	Sorbus aucuparia (Rowan/Mountain Ash)	Due to poor structural/physiological condition in order to prevent failure on to road/ footpath/ third party land.	Planned	In progress	Dec / Feb
50243	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Codicote Road, Wheathampstead	Behind lamp post 0010	Not identified	Dead Tree	Planned	In progress	Dec / Feb
50244	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Codicote Road, Wheathampstead	Behind lamp post 0010	Not identified	Dead Tree	Planned	In progress	Dec / Feb
50245	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Codicote Road, Wheathampstead	Behind lamp post 0010	Not identified	Dead Tree	Planned	In progress	Dec / Feb
50248	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Codicote Road, Wheathampstead	Behind lamp post 0010	Not identified	Dead Tree	Planned	In progress	Dec / Feb
50891	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
50896	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
50900	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
50912	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb

50927	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
51287	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Jenkins Avenue, Bricket Wood	Outside 9	Field maple	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51324	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Juniper Avenue, Bricket Wood	Juniper Avenue, Opposite 1	Whitebeam	Dead Tree	Planned	In progress	Dec / Feb
51327	HT2425-024	Bricket Wood	St Stephen's	St Stephen	Hunters Ride, Bricket Wood	Corner of Hunters Ride/Mount Pleasant Lane	Wild cherry	In decline and poor structural and physiological condition	Planned	In progress	Dec / Feb
51367	HT2425-019	Bricket Wood	St Stephen's	St Stephen	Claremont, Bricket Wood	Opposite 12	Sorbus aria (Whitebeam)	Due to excessive lean and poor structural condition	Planned	In progress	Dec / Feb
51541	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	High Meads, Wheathampstead	Opposite 11	Common hawthorn	Due to poor structural condition	Planned	In progress	Dec / Feb
51624	HT2425-022	Harpenden	Harpenden North East	Harpenden East	Ox Lane, Harpenden	Opposite 57	Elder	Dead Tree	Planned	In progress	Dec / Feb
51627	HT2425-022	Harpenden	Harpenden North East	Harpenden North & Rural	Ox Lane, Harpenden	Outside 1	English elm	Dead Tree	Planned	In progress	Dec / Feb
51650	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Garden Court, Wheathampstead	At junction with Lower Luton Road	Wild cherry	Dead Tree	Planned	In progress	Dec / Feb
51666	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Codicote Road, Wheathampstead	At junction with Cory-Wright Way	Betula pendula (Silver Birch)	Dead Tree	Planned	In progress	December
51692	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	The Hill, Wheathampstead	Side of 1 Butterfield	English elm	Due to poor structural condition	Planned	In progress	Dec / Feb
51702	HT2425-020	St Albans	St Albans East	Cunningham	Cell Barnes Lane, St Albans	Opposite 271	Betula pendula (Silver Birch)	Dead Tree	Planned	In progress	Dec / Feb
51706	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Side of no.25 Lords Meadow	Staghorn sumac	Dead Tree	Planned	In progress	Dec / Feb
51714	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	The Hill, Wheathampstead	Opposite 33/35	Common hawthorn	Dead Tree	Planned	In progress	Dec / Feb
51729	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Outside no.52	Common hawthorn	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51736	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Outside no.52	English elm	Dead Tree	Planned	In progress	Dec / Feb
51742	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Outside no.54	Hazel	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51747	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Outside no.56	English elm	Dead Tree	Planned	In progress	Dec / Feb
51756	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Outside no.62	Mixed species	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51765	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Crouch Hall Lane, Redbourn	Outside no.59	Blackthorn	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51785	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	The Hill, Wheathampstead	Opposite Walnut Court	English elm	Dead Tree	Planned	In progress	Dec / Feb
51807	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Lamb Lane, Redbourn	By lamp post no.8	Leyland cypress	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51809	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Lamb Lane, Redbourn	Second tree from lamp post no.8	Leyland cypress	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51810	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Lamb Lane, Redbourn	To the side of 1a	Elder	Dead Tree	Planned	In progress	Dec / Feb
51814	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Snatchup, Redbourn	Opposite no.13 Long Cut	Common hawthorn	Poor structural and physiological condition	Planned	In progress	Dec / Feb
51881	HT2425-023	St Albans	St Albans North	Batchwood	Ladies Grove, St Albans	Outside 43-45	English elm	Dead Tree	Planned	In progress	Dec / Feb
51901	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Meads Lane, Wheathampstead	Opposite 9	Common ash	Poor Condition	Planned	In progress	Dec / Feb
51903	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Adjacent to 132 Waverley Road	Elder	Dead Tree	Planned	In progress	Dec / Feb
51904	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Adjacent to 132 Waverley Road	English elm	Dead Tree	Planned	In progress	Dec / Feb
51993	HT2425-023	St Albans	St Albans North	Batchwood	High Oaks, St Albans	Side of 101	Japanese crab apple	Dead Tree	Planned	In progress	Dec / Feb
52090	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Gaddesden Lane, Redbourn	On grass bank opposite pond	English elm	Dead Tree	Planned	In progress	Dec / Feb

52091	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Gaddesden Lane, Redbourn	From Hemel Hempstead just before and to the left on the M1 bridge	English elm	Poor structural and physiological condition	Planned	In progress	Dec / Feb
52104	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Gaddesden Lane, Redbourn	On grass bank opposite pond	Common holly	Poor structural and physiological condition	Planned	In progress	Dec / Feb
52153	HT2425-023	Redbourn	Harpenden Rural	Redbourn	High Street, Redbourn	By bus stop at bridge over river Ver	English elm	Poor structural and physiological condition	Planned	In progress	Dec / Feb
52202	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Harding Close, Redbourn	Opposite no. 10	Sycamore	Moderate	Planned	In progress	Dec / Feb
52213	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Harding Close, Redbourn	Opposite no.6	Spruce	Dead Tree	Planned	In progress	Dec / Feb
52228	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Harding Close, Redbourn	Opposite no.6 Opposite 33b Crown street	Common beech	Dead Tree	Planned	In progress	Dec / Feb
52413	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Luton Lane, Redbourn	By drive top of Luton Lane	Sycamore	Dead Tree	Planned	In progress	Dec / Feb
52414	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Luton Lane, Redbourn	At junction with Dunstable Road	Sycamore	Poor structural and physiological condition	Planned	In progress	Dec / Feb
52420	HT2425-023	Redbourn	Harpenden Rural	Redbourn	Luton Lane, Redbourn	Approx 40m on left from junction with Dunstable Road	Common ash	Dead Tree	Planned	In progress	Dec / Feb
52580	HT2425-024	St Albans	St Albans South	Verulam	Antonine Gate, St Albans	Side of no.43	Hazel	Dead Tree	Planned	In progress	Dec / Feb
52599	HT2425-024	St Albans	St Albans South	Verulam	Mayne Avenue, St Albans	Opposite side of no.16 Augustus Close	Field maple	Dead Tree	Planned	In progress	Dec / Feb
52600	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Downy serviceberry	Dead Tree	Planned	In progress	Dec / Feb
52600	HT2425-020	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Amelanchier arborea (Snowy Mespilus)	Dead Tree	Planned	In progress	Dec / Feb
52601	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Downy serviceberry	Dead Tree	Planned	In progress	Dec / Feb
52601	HT2425-020	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Amelanchier arborea (Snowy Mespilus)	Dead Tree	Planned	In progress	Dec / Feb
52602	HT2425-020	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Amelanchier arborea (Snowy Mespilus)	Dead Tree	Planned	In progress	Dec / Feb
52602	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Downy serviceberry	Dead Tree	Planned	In progress	Dec / Feb
52605	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
52608	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
52610	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Common alder	Dead Tree	Planned	In progress	Dec / Feb
52611	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Common alder	Dead Tree	Planned	In progress	Dec / Feb
52622	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Red snakebark maple	Dead Tree	Planned	In progress	Dec / Feb
52631	HT2425-020	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Betula pendula (Silver Birch)	Dead Tree	Planned	In progress	Dec / Feb
52636	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road	Silver birch	Due to poor structural and physiological condition	Planned	In progress	Dec / Feb
52653	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Verge near London Road Cemetery	Silver birch	Dead Tree	Planned	In progress	Dec / Feb
52670	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	On approach from London Colney on the right hand just before roundabout near electrical box	Common hawthorn	Due to poor physiological condition	Planned	In progress	Dec / Feb
52686	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Near road sign, between roundabout and fire station	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb

52690	HT2425-024	St Albans	St Albans South	St Stephen	Watford Road, St Albans		Mixed species	The group of trees show greater than 50% dieback and present risk to highway.	Planned	In progress	Dec / Feb
139500	HT2425-020	St Albans	St Albans Central	Clarence	Hamilton Road, St Albans	Outside 23 Hamilton Road	Betula pendula (Silver Birch)	Due to evident decline.	Planned	In progress	Dec / Feb
139508	HT2425-020	St Albans	St Albans Central	Clarence	Hamilton Road, St Albans	Adjacent to 61 Brampton road	Prunus cerasifera 'Nigra' (Purple Cherry Plum)	Due to suspected hollowing/softening of internal wood. Particularly at base and on roadside that will likely lead to tree failure of allowed to develop.	Planned	In progress	Dec / Feb
139720	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Between lamps 7 and 8	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
139800	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
139818	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Common ash	Poor structural and physical condition	Planned	In progress	Dec / Feb
139819	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett (DF)	From Staff Cottages to Hoban	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
139824	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Goat willow	Dead Tree	Planned	In progress	Dec / Feb
139828	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
139869	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
139885	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Wild cherry	Dead Tree	Planned	In progress	Dec / Feb
139889	HT2425-025	Radlett	St Stephen's	Park Street	Harper Lane, Shenley, Radlett	From Staff Cottages to Hoban	Common hawthorn	Dead Tree	Planned	In progress	Dec / Feb
151210	HT2425-020	St Albans	St Albans Central	St Peters	St Peters Close, St Albans	Outside 10 St Peters Close	Prunus sp. (Cherry sp.)	Dead Tree	Planned	In progress	Dec / Feb
989731	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989732	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989733	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989734	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989735	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989736	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989737	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989738	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Staff Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989759	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Farm Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989760	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Farm Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989770	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite 43 Farm Cottages	English elm	Dead Tree	Planned	In progress	Dec / Feb
989774	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Hadleigh Close	English elm	Dead Tree	Planned	In progress	Dec / Feb
989776	HT2425-025	Radlett	London Colney	London Colney	Harper Lane, Shenley, Radlett	Opposite Hadleigh Close	English elm	Dead Tree	Planned	In progress	Dec / Feb
990315	HT2425-020	St Albans	St Albans South	Sopwell	Watting View, St Albans	Opposite school	Sorbus sp. (Sorbus sp.)	Dead Tree	Planned	In progress	Dec / Feb
990317	HT2425-020	St Albans	St Albans South	Sopwell	Watting View, St Albans	Opposite school	Sorbus sp. (Sorbus sp.)	Dead Tree	Planned	In progress	Dec / Feb
990320	HT2425-020	St Albans	St Albans Central	Clarence	Sandpit Lane, St Albans	Opposite 89c	Acer pseudoplatanus (Sycamore)	Dead Tree	Planned	In progress	Dec / Feb



990384	HT2425-019	St Albans	London Colney	Hill End	Highfield Lane, Tyttenhanger, St Albans	By Highfield Park entrance and crossing	Acer pseudoplatanus (Sycamore)	Regenerating stump with maturing epicormic growth the prevent failure of epicormic stems onto road and footpath due to decayed attachment points.	Planned	In progress	Dec / Feb
990398	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Sleepshyde, Smallford	Opposite Thanet House	English Elm (group of 14)	Dead Tree	Planned	In progress	Dec / Feb
990439	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Oaklands Lane, Smallford	Behind lamp post 216	Fraxinus excelsior (Ash)	Due to decay related fungal colonisation on lower stem, to prevent failure into footpath or road.	Planned	In progress	Dec / Feb
990441	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Oaklands Lane, Smallford	Behind lamp post 216	Fraxinus excelsior (Ash)	Due to decay related fungal colonisation on lower stem, to prevent failure into road.	Planned	In progress	Dec / Feb
990461	HT2425-019	Bricket Wood	St Stephen's	Park Street	Birchwood Way, Bricket Wood	Outside 27	Prunus cerasifera 'Atropurpurea' (Cherry Plum (Myrobalan))	Fell due to 50% canopy failure	Planned	In progress	Dec / Feb
990467	HT2425-019	Smallford	Colney Heath & Marshalswick	Colney Heath	Oaklands Lane, Smallford	Behind lamp post 216	Ilex aquifolium (Holly)	Dead Tree	Planned	In progress	Dec / Feb
990476	HT2425-019	Bricket Wood	St Stephen's	Park Street	Birchwood Way, Bricket Wood	Outside 91	Sorbus aucuparia (Rowan/Mountain Ash)	Due to poor structural/physiological condition in order to prevent failure on to road/ footpath/ third party land.	Planned	In progress	Dec / Feb
990600	HT2425-008	St Albans	St Albans North	Batchwood	Batchwood, St Albans	From lamp 329 to 328	Acer pseudoplatanus (Sycamore)	Dead Tree	Planned	In progress	December
990655	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 78	Pinus sp. (Pine sp.)	Dead Tree	Planned	In progress	December
990656	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 78	Fraxinus excelsior (Ash)	Dead Tree	Planned	In progress	December
990657	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 78	Fraxinus excelsior (Ash)	Dead Tree	Planned	In progress	December
990658	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Church Lane, Colney Heath	Boundary of St Marks Church	Quercus Robur (English Oak)	Dead Tree	Planned	In progress	Dec / Feb
990669	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Fellowes Lane, Colney Heath	Near Junction with Bullens Green Lane	English Elm (group of 6)	Dead Tree	Planned	In progress	Dec / Feb
990685	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	Bullens Green Lane, Colney Heath	Outside 10-12	Sorbus cashmiriana (Kashmir Rowan)	Dead Tree	Planned	In progress	Dec / Feb
990687	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 90	unrecognized (Unrecognised)	Dead Tree	Planned	In progress	December
990705	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Opposite 98	Crataegus monogyna (Common Hawthorn/Quick/May)	Dead Tree	Planned	In progress	December
990716	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Near junction with Leasy Bridge Lane	Pinus sylvestris (Scots Pine)	Dead Tree	Planned	In progress	December
990730	HT2425-008	Wheathampstead	Harpenden Rural	Harpenden South	Wheathampstead Road, Harpenden	Near junction with Leasy Bridge Lane	Pinus sylvestris (Scots Pine)	Dead Tree	Planned	In progress	December
990978	HT2425-020	St Albans	St Albans North	Batchwood	Batchwood, St Albans	To the left of the entrance to Batchwood Gold Course	Acer pseudoplatanus (Sycamore)	Dead Tree	Planned	In progress	Dec / Feb
991008	HT2425-019	Colney Heath	Colney Heath & Marshalswick	Colney Heath	High Street, Colney Heath	Verge outside 96-106	Malus sp. (Apple sp.)	Dead Tree	Planned	In progress	Dec / Feb
991029	HT2425-020	Sandridge	Harpenden Rural	Sandridge & Wheathampstead	Church End, Sandridge	Opposite The Queens Head pub	Sambucus nigra (Elder)	Drowning around lamp column. Inappropriate location.	Planned	In progress	Dec / Feb
991034	HT2425-020	Sandridge	Harpenden Rural	Sandridge & Wheathampstead	Woodcock Hill, Sandridge	Opposite Sandridge School	Quercus Robur (English Oak)	to clear street light (tree growing under street light).	Planned	In progress	Dec / Feb

991035	HT2425-019	St Albans	St Albans East	Cunningham	Highfield Park Drive, St Albans	Behind lamp no.4	Betula pendula (Silver Birch)	Dead Tree	Planned	In progress	Dec / Feb
991045	HT2425-020	St Albans	London Colney	Hill End	Hill End Lane, St Albans	Sovereign Park junction	Acer platanoides (Norway Maple)	Dead Tree	Planned	In progress	Dec / Feb
991367	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead		Pedunculate oak	Poor structural and physical condition	Planned	In progress	Dec / Feb
991368	HT2425-022	Wheathampstead	Harpenden Rural	Sandridge & Wheathampstead	Marshalls Heath Lane, Wheathampstead	Opposite Farndale Marshalls Heath Lane	English elm	Dead Tree	Planned	In progress	Dec / Feb
994255	HT2425-022	Harpenden	Harpenden South West	Harpenden South	West Common Grove, Harpenden		Common ash	Poor structural and physical condition	Planned	In progress	Dec / Feb
994257	HT2425-022	Harpenden	Harpenden South West	Harpenden South	West Common Grove, Harpenden	Opposite 17	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
994258	HT2425-022	Wheathampstead	Harpenden South West	Harpenden South	West Common Grove, Harpenden	Opposite 17	Common ash	Due Ash Dieback Infection Level 3: 50% to 75%	Planned	In progress	Dec / Feb
996002	HT2425-025	St Albans	St Albans East	Cunningham	London Road, St Albans	Near Admirals Walk greenspace	Not identified	Dead Tree	Planned	In progress	Dec / Feb
996011	HT2425-023	St Albans	St Albans North	Batchwood	Everlasting Lane, St Albans	Adjacent to 81 White Hedge Drive	Field maple	Dead Tree	Planned	In progress	Dec / Feb